Vendor: Cisco

Exam Code: 500-920

Exam Name: Cisco Data Center Unified Computing

Infrastructure Troubleshooting

Version: DEMO

QUESTION 1
Which command sequence is required to reset Cisco Integrated Management Controller (IMC) of a Cisco UCS Server?

A. connect cimc | reset | validate
B. scope cimc | reset | commit-buffer
C. connect cimc | reset | commit
D. scope cimc | reset | validate

Answer: B

QUESTION 2
When configuring UCS SAN Connectivity to a 3rd Party FibreChannel Storage Array that is connecting directly to the UCS Fabric Interconnects, which option is Cisco recommended'?

A. Connect the Storage Array to a RC Storage Port and Enable NPV Mode on the UCS Fabric Interconnects
B. Connect the Storage Array to an Appliance Port and Enable NPV Mode on the UCS Fabric Interconnects
C. Direct connectivity between UCS Fabric Interconnects and FibreChannel Storage Arrays is not supported
D. Connect the Storage Array to a FC Storage Port and Enable Switching Mode on the UCS Fabric Interconnects
E. Connect the Storage Array to an Appliance Port and Enable Switching Mode on the UCS Fabric Interconnects

Answer: D

QUESTION 3
An overvoltage condition has occurred on a UCS server However the Cisco IMC System Event Log (SEL) file is full What is the resulting fault logging action?

A. The newest entry in the SEL will be overwritten by the overvoltage condition event.
B. The oldest entry in the SEL will be overwritten by the overvoltage condition event
C. The SEL is not used to record server related events, such as overvoltage conditions.
D. The overvoltage condition event will not be recorded in the SEL.

Answer: D

QUESTION 4
Which two ports on a pair of Cisco Fabric Interconnects must be properly cabled for the pair to form a cluster? (Choose two)

A. L1 > L1
B. L1 > L2
C. L2 > L2
D. L2 > L1

Answer: AC

QUESTION 5
Which two components are required when the integration of Cisco UCS C-series servers within a Cisco UCS Manager Direct Connect mode? (Choose two)

A. Compatible Cisco Nexus Fabric Extenders
B. Cisco Management Controller
C. Compatible UCS VIC adapter installed via the server's PCIe or MLOM slot
D. Compatible UCS 6200 or 6300 Fabric Interconnects
E. Compatible Cisco UCS Manager version

Answer: CD

QUESTION 6
The UCS Chassis Discovery Policy has been set to four and a new chassis is connected with two links What is the resulting chassis recognition action?

A. The chassis will not be recognized
B. The Chassis Discovery Policy will automatically reset to two links, since it always tracks the physical connections
C. The chassis will be recognized and both links will be active
D. The chassis will be recognized but only one of the links will be active.

Answer: A

QUESTION 7
When troubleshooting UCS initialization issues that require Fabric Interconnect reboots, which Fabric Interconnect should be rebooted first?

A. The primary Fabric Interconnect
B. Both Fabric Interconnects must be rebooted simultaneously
C. The Cisco UCS Manager will determine with Fabric Interconnect to reboot
D. The subordinate Fabric Interconnect

Answer: A

QUESTION 8
The command show interface veth 705 is telling you that the bound interface is Ethernet 3/1/2 What is the location of the blade that has veth 705 associated to it?

A. Chassis 3, Slot 1
B. Chassis 3. Slot 2
C. There is not enough information
D. Chassis 1. Slot 2

Answer: A

Thank You for Trying Our Product

Lead2pass Certification Exam Features:

★ More than **99,900** Satisfied Customers Worldwide.

★ Average **99.9%** Success Rate.

★ **Free Update** to match latest and real exam scenarios.

★ **Instant Download** Access! No Setup required.

★ Questions & Answers are downloadable in **PDF** format and **VCE** test engine format.

★ Multi-Platform capabilities - **Windows, Laptop, Mac, Android, iPhone, iPod, iPad**.

★ **100%** Guaranteed Success or **100%** Money Back Guarantee.

★ **Fast**, helpful support **24x7**.

View list of all certification exams: http://www.lead2pass.com/all-products.html

10% Discount Coupon Code: ASTR14