



**Vendor:** HP

**Exam Code:** HP0-J56

**Exam Name:** 3PAR Solutions Advanced Service and Support

**Version:** DEMO

#### QUESTION 1

What is introduced in HP 3PAR V-Class arrays?

- A. Mainframe connectivity
- B. Heterogeneous Peer Motion
- C. ProLiant-based service processor
- D. 10 GB iSCSI ports

**Answer: B**

#### QUESTION 2

What is the maximum number of DC4 chassis per V400 controller pair?

- A. 4
- B. 10
- C. 12
- D. 16

**Answer: A**

#### QUESTION 3

When completing SA Document, you customer selected the Secure Site option. After the installation is complete, you noticed there is no remote access to the HP 3PAR storage system. The customer confirms this was in error, and they intended that the inbound/outbound communication access should be via an SSH session. How do you reconfigure the network mode to allow the outbound communication?

- A. Rebuild the Service Processor: re-run the SP MOB, and select SP Mode.
- B. Re-run the OOTB scripts, selecting Secure Services Mode.
- C. Re-run the SP MOB script, selecting Controlled Access Mode.
- D. Edit the network configuration on the controller node, and select SP Mode.

**Answer: D**

#### QUESTION 4

Which command can be used to install 3PAR licenses?

- A. cfglic
- B. licensecfg
- C. licenseadd
- D. setlicense

**Answer: D**

#### QUESTION 5

You are completing an installation of an HP 3PAR V400. Reviewing the output of the health check, you notice the messages displayed on the exhibit. What can you conclude from these messages?

Port	Port:0:5:1	Port mode is in unknown state
Port	Port:0:5:1	Mismatched mode type
Port	Port:0:5:1	Port is config_Wait
Port	Port:0:5:2	Port mode is in unknown state
Port	Port:0:5:2	Mismatched mode type
Port	Port:0:5:2	Port is config_Wait
Port	Port:1:5:1	Port mode is in unknown state
Port	Port:1:5:1	Mismatched mode type
Port	Port:1:5:1	Port is config_Wait
Port	Port:1:5:2	Port mode is in unknown state
Port	Port:1:5:2	Mismatched mode type
Port	Port:1:5:2	Port is config_Wait

- A. There is an unconfigured CAN in each node
- B. The Fibre Channel Host ports are unconfigured
- C. An unsupported adapter has been installed
- D. The InForm OS needs to be patched

**Answer: B**

#### QUESTION 6

When adding new components to an existing system, which statement is correct?

- A. Install the 3PAR Upgrade licenses before adding new components to the system
- B. Make sure that the configurations are consistent with best practices
- C. Verify that the primary CPG is taken offline before adding new drives to the system
- D. Verify that the components to install have the latest firmware installed

**Answer: D**

## Thank You for Trying Our Product

### Lead2pass Certification Exam Features:

- ★ More than **99,900** Satisfied Customers Worldwide.
- ★ Average **99.9%** Success Rate.
- ★ **Free Update** to match latest and real exam scenarios.
- ★ **Instant Download** Access! No Setup required.
- ★ Questions & Answers are downloadable in **PDF** format and **VCE** test engine format.
- ★ Multi-Platform capabilities - **Windows, Laptop, Mac, Android, iPhone, iPod, iPad**.
- ★ **100%** Guaranteed Success or **100%** Money Back Guarantee.
- ★ **Fast**, helpful support **24x7**.



View list of all certification exams: <http://www.lead2pass.com/all-products.html>



Microsoft



ORACLE



CITRIX



JUNIPER  
NETWORKS



EMC<sup>2</sup>  
where information lives®

**10% Discount Coupon Code: ASTR14**