



Vendor: Hitachi

Exam Code: HQT-4180

Exam Name: Hitachi Vantara Qualified Professional VSP
Midrange Family Installation

Version: DEMO

QUESTION 1

You are installing a new VSP G700 and are using the Initial Setup Wizard (ISW) for the network configuration.

Which set of IP addresses is configured with the ISW?

- A. IP addresses of maintenance ports
- B. IP addresses of management ports
- C. IP addresses of all the ports
- D. IP addresses of all the ports and of the SVP

Answer: B

QUESTION 2

You are installing a VSP F370 and you need to connect your laptop to one of the controllers.

What are the two default IP addresses of the maintenance ports of CTL1 and CTL2? (Choose two.)

- A. 10.0.0.17
- B. 10.0.0.16
- C. 192.168.0.17
- D. 192.168.0.16

Answer: BD

QUESTION 3

Which tool do you use to install license keys on a VSP G370 system?

- A. HSA Embedded
- B. MPC Software
- C. Storage Navigator
- D. Maintenance Utility

Answer: D

QUESTION 4

Which tool monitors a VSP E590 system and reports System Information Messages (SIMs)?

- A. Hitachi Remote Ops Monitor Agent
- B. Hitachi Remote Ops SVP Agent
- C. Hitachi Ops Center Protector
- D. Storage Navigator

Answer: C

QUESTION 5

Which two statements are correct when adding cache to a VSP E590? (Choose two.)

- A. Cache modules must be installed in CMG1.
- B. Cache Modules must be installed on the CM board.

- C. CMG0 and CMG1 must have the same DIMM type.
- D. This is not supported online.

Answer: AC

QUESTION 6

A customer wants to change a production RAID Group from RAID 5 (7D+1P) to RAID 6 (6D + 2P) on a VSP G700 during normal operations. They have just unmapped the LUNs from the channel ports.

What needs to be performed next?

- A. The RAID level must be changed in Storage Navigator.
- B. The RAID level must be changed in the SVP Maintenance window.
- C. The RAID 5 Group must be put into DRU mode in Storage Navigator.
- D. The RAID Group must be deleted.

Answer: B

QUESTION 7

Which tool can be used to change System Option Modes (SOMs)?

- A. Hitachi Ops Center
- B. Webconsole
- C. HSAe
- D. MPC software

Answer: D

QUESTION 8

You have to perform a firmware update containing new code for DKCMain, CHBs and drives on a VSP G900.

What are two requirements? (Choose two.)

- A. The CHBs must be updated first.
- B. The Microprocessor utilization should be below 50%.
- C. The Cache Write Pending rate should be below 30%.
- D. There should be no sparing processes running in the background.

Answer: AD

Thank You for Trying Our Product

Lead2pass Certification Exam Features:

- ★ More than **99,900** Satisfied Customers Worldwide.
- ★ Average **99.9%** Success Rate.
- ★ **Free Update** to match latest and real exam scenarios.
- ★ **Instant Download** Access! No Setup required.
- ★ Questions & Answers are downloadable in **PDF** format and **VCE** test engine format.
- ★ Multi-Platform capabilities - **Windows, Laptop, Mac, Android, iPhone, iPod, iPad**.
- ★ **100%** Guaranteed Success or **100%** Money Back Guarantee.
- ★ **Fast**, helpful support **24x7**.



View list of all certification exams: <http://www.lead2pass.com/all-products.html>



Microsoft



ORACLE



JUNIPER
NETWORKS



EMC²
where information lives

10% Discount Coupon Code: ASTR14